

Unismart Product Unavailable Notification

17th May, 2016







Samsung 117/504/506/116/204 2M Series Replacement Chip









Apex has replaced the 2M series chips with 4S series chips in November, 2015, so the 2M series chips are unavailable now. And in December, 2015, Samsung updated firmware in its printers with MLT-D101/358/405/505/111/203 cartridges, thus the Unismart device stopped resetting the MLT-D101/358/405/505/111/203 with 2M series chips. Later, Samsung updated firmware again in its printers with MLT-D117/504/506/116/204 cartridges, which caused Apex 2M replacement chips shipped before 2016 failed recognition. To ensure the chip's performance, Apex decided to upgrade the Unismart system at the end of June and suspend the resetting function of 2M series chips. Please contact Apex sales managers to replace empty chips.

Please wait for related upgraded firmware version until further notice.

Note: please tick the product list and system when update the package.

Model List:

U Character	Old PCB Code (Unavailable)	Apply to	New PCB Code (Available)	Apply to
S1	CC2M2210 	Samsung-117/50 4/506 Dell-1160/2375	CC4S2240 	Samsung-101/11 7/504/506 Dell-1160/2375
S2	CC2M3C10  CC2M3210  CC2M3950 	Samsung 406	CC4S3230 	Samsung 406

<p>S3</p>	<p>CC2M2510</p>  <p>CC2M2520</p>  <p>CC2M2920</p> 	<p>Samsung 115 series solution C Xerox-2773</p>	<p>CC4S2530</p> 	<p>Samsung 115 series solution C Xerox-2773</p>
<p>S4</p>	<p>CC2M3510</p>  <p>CC2M3520</p>  <p>CC2M3620</p> 	<p>Samsung 115 series solution C</p>	<p>CC4S3540</p>  <p>Note: U character is OS4 (replace the U character S4)</p>	<p>Samsung 115 series solution C</p>

Please contact your sales manager for more information!

“Apex” herein refers to Apex Microelectronics Co., Ltd. The information contained herein is subject to change without prior notification. Apex shall not be liable for technical or editorial errors or omissions contained herein. Photographed products may not always match the description.